

Shepherd labs fire July 13, 2010



South side of the room



Fire and smoke source



Fire damage 398 Shepherd Labs – source on table






Possible source – Battery charger moved from middle of burnt material



Spray foam from container on table on the ceiling



Materials on the south side of the room- Spray foam discharged to the east



Soot on the ceiling



Materials on the north side



Materials moved on the north side showing soot buildup.